## IN THE UNITED STATES PATENT & TRADEMARK OFFICE

ATTORNEY DOCKET NUMBER: 10992517-3

IN RE APPLICATION OF: U.S. Patent No. 7,087,946

USPTO CONFIRMATION CODE: 8317

APPLICATION NO.: 10/697,589

FILED: Oct. 30, 2003

EXAMINER: Howard Weiss

GROUP ART UNIT: 2814

FOR: ELECTRIC DEVICE HAVING NANOSCALE WIRES AND GAPS

## 37 CFR 1.322 & 37 CFR 1.323 REQUEST FOR CERTIFICATE OF CORRECTION

## HONORABLE COMMISSIONER OF PATENTS & TRADEMARKS

charge the amount to the same Deposit Account.

Sir:

The following is a request for a certificate of correction in Serial Number 10/697.589, now Patent Number 7.087.946.

A certificate of correction under 35 USC 254 is respectfully requested in the above-identified patent.

$\bowtie$	All errors were the fault of the USPTO, no fee required. In the event that a further
fee is	required, please charge the amount to Deposit Account No. 082025.
	All errors were the fault of the applicant and, accordingly, please charge \$100.00
to our	Deposit Account No. 082025. In the event that a further fee is required, please

The errors were the fault of both the applicant and USPTO and, accordingly, please charge \$100.00 to our Deposit Account No. 082025. In the event that a further fee is required, please charge the amount to the same Deposit Account.

The exact locations where the errors appear in the patent and patent application are as follows:

In column 4, line 14, after "Ho," delete "Th," and insert -- Tb, --, therefor. (Specification filed on Oct. 30, 2003, page 5, line 28)

The requested corrections are attached on Form PTO 1050.

Respectfully Submitted

March 5, 2010 DATE /David W. Collins/ Name: David W. Collins Registration No.: 26,857

Attorney/Agent of Record

HEWLETT-PACKARD COMPANY Intellectual Property Administration 3404 E. Harmony Road Mail Stop 35 Fort Collins, CO 80528

## UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Page 1 of 1

PATENT NO. : 7,087,946

APPLICATION NO.: 10/697,589

ISSUE DATE : Aug. 08, 2006

INVENTOR(S) : Yong Chen, et al.

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In column 4, line 14, after "Ho," delete "Th," and insert - - Tb, - -, therefor.

MAILING ADDRESS OF SENDER (Please do not use customer number below):

HEWLETT-PACKARD COMPANY Intellectual Property Administration 3404 E. Harmony Road Mail Stop 35 Fort Collins, CO 80528

This collection of information in required by Y CPR L22, and J 92, and L234 Th. information is required to obtain or retain a brand by the public whech is to fit in and by the LSPP to process an application. Confidentiable sy governed by \$3 U.S.C. 122 and \$3 CPR 1.4.1 This collection is estimated to take 10 loss to be the proceeding by the process in the public which is the process of the proc